HISTORIC AMERICAN ENGINEERING RECORD

HAER PA 4-AMB.V

INDEX TO PHOTOGRAPHS

OHIO SLACK WATER DAMS, LOCK AND DAM No. 4

East bank of the Ohio River at mile point 18.6, along Route 65

Ambridge Vicinity
Beaver County
Pennsylvania

PHOTOGRAPHER:	(VIEWS 1-11) RICHARD WILLIAMS	NOVEMBER 1992/APRIL 1993
PA-227-A-1	VIEW LOOKING EAST AT LOWER GATE RECESS AND LOWER GUIDE WALL FROM THE OHIO RIVER.	
PA-227-A-2	VIEW LOOKING EAST AT STEPS AND CENTER OF THE LOCK COMPLEX), FRO	
PA-227-A-3	VIEW LOOKING EAST AT UPPER GATE RE (NOTE: REMAINS OF TRACKS FROM RO SUBMERGED.)	
PA-227-A-4	VIEW LOOKING EAST AT UPPER GATE RE	ECESS FROM THE OHIO RIVER.
PA-227-A-5	VIEW LOOKING NORTHEAST AT UPPER GUIDE WALL REMAINS AND LAND WALL FROM THE OHIO RIVER.	
PA-227-A-6	VIEW OF DISTURBANCE IN THE LOW NORTHEAST.	ER GATE RECESS LOOKING
PA-227-A-7	VIEW OF THE FOUNDATION OF 1 (NORTHERN MOST), LOOKING NORTH.	THE LOCKTENDERS HOUSE
PA-227-A-8	VIEW OF THE FOUNDATION OF T (SOUTHERN MOST), LOOKING WEST.	THE LOCKTENDERS HOUSE
PA-227-A-9	VIEW OF UPPER LOCK RECESS SHOWIN LOOKING WEST.	G SUBMERGED GATE TRACKS,
PA-227-A-10	VIEW OF SUBMERGED DRIFT CHUTE IN NORTHEAST CORNER OF UPPER GATE RECESS, LOOKING NORTHEAST.	
PA-227-A-11	VIEW OF THE REMAINS OF THE ESPLAI	NADE LOOKING SOUTH.

